



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**

**Date:**

July 7, 2010

Reviewed: 

<b>Mine Name:</b> County Canyon Shale	<b>Permit Number:</b> M230024
<b>Operator Name:</b> Ash Grove Cement Company	<b>Inspection Date:</b> June 24, 2010
<b>Inspector(s):</b> Wayne Western	<b>Time:</b> 3:00 pm – 3:20 pm
<b>Other Participants:</b> none	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:**

**Permit fee:**

**Purpose of Inspection:**

This is a routine inspections.

**Inspection Summary:**

The shale has been mined and stockpiled on site. The mine not being actively mined and only will be excavated in a downward direction (the floor of the mine will be lowered) having met the boundary of the deposit.

**Directions to Site:**

The site sits west of Nephi on Route 132 route (1812) east of the town of Leamington. Turn off is approximately 4.3 mile west of turn off onto 1812. Follow well kept road.

**Conclusions and Recommendations:**

The Division should continue to monitor the site.


**Inspector's Signature**

WHW

cc: (OPERATOR)

Jerry Mansfield BLM

O:\M023-Juab\M0230024-CountyCanyon\Draft\ins-M0230024\_07142009.doc







Pit



Pit